ASP-MG2240 Software Install Notes

The 64bit.exe which is the driver installer application will copy the related USB driver files into the system folder, so that some antivirus software may consider it as the Trojan virus because the copy behavior found. End user need to disable the antivirus software or allow antivirus to ignore this warning manually when installing USB drivers. This warning only can be solved by install the driver manually instead of installer application, it means that user cannot use the installer and need to install manually using Windows Device Manager.